

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/9	MAKE	KATO	MODEL	KRM-20H
SERIAL No.	PLATE :	7010055		STAMP :	KRC014-0055
HR METER	20916	HR	Odometer	145030	km
TIRE SIZE	325/95R24		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	

OPERATION PUMP

Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	

COOLING SYSTEM

Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	

OPERATING SYSTEM

Computer	<input checked="" type="radio"/> OK	NG	
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	

TRANSMISSION

Transmission	<input checked="" type="radio"/> FAIR	Attn	*1
No. OF GEARS	4	GEARS	
4WD	<input checked="" type="radio"/> 4WD	<input type="radio"/> 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	<input checked="" type="radio"/> CLEAN	FAIR	DIRTY		
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn			
Glasses	<input checked="" type="radio"/> FAIR	Attn			
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C	<input type="radio"/> H only	<input type="radio"/> C only	<input type="radio"/> None

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR	Attn	
DERRICKING CYL.	<input checked="" type="radio"/> FAIR	Attn	
EXTENSION CYL.	<input checked="" type="radio"/> FAIR	Attn	
JIB	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
JIB TYPE	<input type="radio"/> STD	<input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
FREE FALL	<input type="radio"/> YES	<input checked="" type="radio"/> NO	
HOOK	20t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	FAIR · WORN <input checked="" type="radio"/> UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	X	<input checked="" type="radio"/> H				
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR	Attn				
Oil leakage (JACK CYL.)	FRONT	<input type="radio"/> L	<input type="radio"/> R	REAR	<input type="radio"/> L	<input type="radio"/> R
Oil leakage (SLIDE CYL.)	FRONT	<input type="radio"/> L	<input type="radio"/> R	REAR	<input type="radio"/> L	<input type="radio"/> R

COMMENT

エアータンク:エア漏れあり AIR TANK: AIR LEAKING	
穴あり MUCH HOLES	
ロータリー付近にじみあり AROUND ROTARY: OIL OOZING	
*1 ミッション付近にじみあり AROUND TRANSMISSION: OIL OOZING	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。