# INSPECTION SHEET 検品書

## GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2026/5/21 | CATEGORY | (GENERATOR) / COMPRESSOR / WELDER | | |
| MAKE | DENYO | | MODEL | DCA-150LSKE | |
| SERIAL | 3909976 | | STAMP | NOT FOUND | |
| HR METER | 1052 HR | TIRE SIZE | | YEAR | YR |

| ENGINE : | MODEL | KOMATSU 6D107E-1 | S/N | 26648779 | |
|---|---|---|---|---|---|
| Oil leakage | (FAIR) · Attn | | Oil | (FAIR) · Attn | |
| Blow-By | (FAIR) · Attn | A LITTLE · MIDDLE · SEVERE | Exhaust Color | (FAIR) · Attn | |
| Sound | (FAIR) · Attn | | Radiator | (FAIR) · Attn | |

| GENERATOR | | | | | |
|---|---|---|---|---|---|
| RATED POWER | 125 / 150 | KVA | Leaking Breaker Condition | (FAIR) · Attn | |
| RATED AMPERE | 361, 180 / 394, 197 | A | Insulation Condition | (FAIR) · Attn | |
| Output Terminal | (FAIR) · Attn | | | | |

| COMPRESSOR | | | | | |
|---|---|---|---|---|---|
| RATED PRESSURE | Mpa Kgf/cm2 | | Unload Condition | FAIR · Attn | |
| RATED AIR FLOW | m3/min | | Receiver Tank Condition | FAIR · Attn | |
| Compressor Oil Leak | FAIR · Attn | | Safety Valve Condition | FAIR · Attn | |

| CONDITION | (FAIR) · Attn | |
|---|---|---|

| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 | TIRE WEAR | FAIR · WORN · UNEVEN WEAR |
|---|---|---|---|

**COMMENTS**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。