

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2026/5/19	MAKE	CAT	MODEL	D5K2LGP
SERIAL	CAT00D5KERRE02222			STAMP	CAT00D5KERRE02222
HR METER	3313	HR	SHOE	770LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

<b>ENGINE : MODEL</b> C4.4		<b>S/N</b> W7N23722	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	<input checked="" type="radio"/> YES · NO		
<b>OPERATION PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Power	<input checked="" type="radio"/> FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	<input checked="" type="radio"/> PS · DD	DIFF. STEERING	YES · <input checked="" type="radio"/> NO
Transmission	<input checked="" type="radio"/> FAIR · Attn		
Travel	<input checked="" type="radio"/> FAIR · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn		
Glasses	<input checked="" type="radio"/> FAIR · Attn		
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None		
<b>BLADE &amp; CYLINDERS</b>			
BLADE	<input checked="" type="radio"/> FAIR · Attn		
CYLD.(R)	<input checked="" type="radio"/> FAIR · Attn		
CYLD.(L)	<input checked="" type="radio"/> FAIR · Attn		
TILT CYLD	<input checked="" type="radio"/> FAIR · Attn		
ANGLE CYLD	<input checked="" type="radio"/> FAIR · Attn	メッキ剥がれあり COATING: PEELED	

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
<b>COMMENT</b>			
<div style="border: 1px dashed black; min-height: 100px;"></div>			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<input checked="" type="radio"/> FAIR · Attn		
<b>COMMENT</b>			
<div style="border: 1px dashed black; min-height: 100px;"></div>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。