INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2026/6/5	MAKE	KOMATSU	MODEL	GD313H
SERIAL	3405			STAMP	GD313H-3405
HR METER	E7796 HR	Odometer	– km	YEAR	YR
SCARIFIER	YES ・ (NO)	*1		BLADE	3050 mm
CAB/CNP	(CAB) / CNP / NONE			TIRE SIZE	11.00-20

ENGINE : MODEL 4D120 S/N 84664		
Oil leakage	FAIR ・(Attn)	E/Gブロックにじみあり ENGINE BLOCK: OIL OOZING
Blow-By	(FAIR)・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	FAIR ・(Attn)	黒煙あり BLACK FUMES
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・(Attn)	オイル混入あり OIL: MIXED
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS ・(DD)	
Transmission	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	効き甘い BRAKE: LOOSE
PARKING BRAKE	FAIR ・(Attn)	*2
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ FAIR ・ (DIRTY)	
Operator's Seat	(FAIR)・ Attn	ガタ、破れあり LOOSE, HUGE CUTS
Glasses	(FAIR)・ Attn	
AirCon	A/C ・ H/C ・ (H only) ・ C only ・ None	
HYD. CYLINDER		
For Blade	(FAIR)・ Attn	
For Scarifier	(FAIR)・ Attn	
Articulate	FAIR ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR (FAIR ・WORN ・ UNEVEN WEAR	
COMMENT	
ステアリングシリンダーにじみあり(カバーあり)	
STEERING CYLINDER: OIL OOZING (W/CYLINDER BOOT)	
サークル旋回モーター油漏れ小 CIRCLE DRIVE MOTOR: OIL LEAKING	
右リアブレーキ配管補修跡あり REAR RIGHT BRAKE PIPE: REPAIRED	
燃料フィルタードレーンにじみあり FUEL FILTER DRAIN: OIL OOZING	
HRメーターストップ HR METER: STOPPED	
*1 シリンダーあり(スカリ欠) W/CYLINDER (SCARIFIER: MISSING)	
*2 効くが効いた位置でレバーロックがされないため機械が動く	
*2 LEVER: UNABLE TO STAY AT THE LOCKED POSITION	
(BRAKE: ABLE TO WORK BUT RELEASING)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。