

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

| | | | | | |
|-----------------|----------------|------|----------|----------------|-------------------|
| INSPECTION DATE | 2026/6/2 | MAKE | TADANO | MODEL | AT-157-1 |
| SERIAL No. | PLATE : 375714 | | | STAMP : 375714 | |
| HR METER | 2811 | HR | Odometer | 33360 | km YEAR YR |
| CHASSIS | MODEL NKR85 | | | No. 7004281 | |
| SHOE | | | | TIRE SIZE | 205/85R16 |
| MAX HIGHT | 15.7 | | | m | MAX WEIGHT 200 kg |

| | |
|---------------------------------------|--|
| ENGINE : MODEL 4JJ1 S/N 597957 | |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Blow-By | <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil | <input checked="" type="radio"/> FAIR · Attn |
| Exhaust Color | <input checked="" type="radio"/> FAIR · Attn |
| US EPA | YES <input checked="" type="radio"/> NO |
| OPERATION PUMP | |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Power | <input checked="" type="radio"/> FAIR · Attn |
| COOLING SYSTEM | |
| Radiator | <input checked="" type="radio"/> FAIR · Attn |
| Oil Cooler | <input checked="" type="radio"/> FAIR · Attn |
| TRANSMISSION & TRAVEL | |
| T/M TYPE | AT <input checked="" type="radio"/> MT No. OF GEARS 6 GEARS |
| Transmission | <input checked="" type="radio"/> FAIR · Attn |
| 4WD | 4WD <input checked="" type="radio"/> 2WD |
| Travel | <input checked="" type="radio"/> FAIR · Attn |
| Swing | <input checked="" type="radio"/> FAIR · Attn |
| FOOT BRAKE | <input checked="" type="radio"/> FAIR · Attn |
| PARKING BRAKE | <input checked="" type="radio"/> FAIR · Attn |
| BOOM | |
| No. of Section | 3 SECTIONS |
| DERRICKING CYL. | <input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1 |
| EXTENSION CYL. | <input checked="" type="radio"/> FAIR · Attn |

| | |
|--|---|
| INTERIOR See Photos. 写真参照 | |
| INTERIOR COND. | <input checked="" type="radio"/> CLEAN · FAIR · DIRTY |
| Operator's Seat | <input checked="" type="radio"/> FAIR · Attn |
| Glasses | <input checked="" type="radio"/> FAIR · Attn |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| TIRE WEAR | <input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR |
| COMMENT | |
| OUTRIGGERS X · <input checked="" type="radio"/> H | |
| OUTRIGGERS COND. | <input checked="" type="radio"/> FAIR · Attn |
| COMMENT | |
| 最高出力 MAXIMUM OUTPUT: 110kW/2800rpm | |
| *1 前側メッキ剥がれあり CYLINDER FOR BASKET: COATING PEELED | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | |
| 3 | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。