INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/6/2	MAKE	HITACHI	MODEL	HX120B-2
SERIAL No.	PLATE : HCM1M400V00001111		STAMP : HCM1M400V00001111		
HR METER	1741 HR	Odometer	– km	YEAR	YR
CHASSIS	MODEL –		No. –		
SHOE	400G PADS		TIRE SIZE		
MAX HIGHT	12.0 m		MAX WEIGHT	250 kg	

ENGINE : MODEL D1105 S/N 7W1505		
Oil leakage	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR ・ Attn	
Oil	FAIR ・ Attn	
Exhaust Color	FAIR ・ Attn	
US EPA	YES ・ NO	
OPERATION PUMP		
Sound	FAIR ・ Attn	
Oil leakage	FAIR ・ Attn	
Power	FAIR ・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・ Attn	
Oil Cooler	FAIR ・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT ・ MT	No. OF GEARS 2 GEARS
Transmission	FAIR ・ Attn	
4WD	4WD ・ 2WD	
Travel	FAIR ・ Attn	
Swing	FAIR ・ Attn	ガタあり SWING: LOOSE
FOOT BRAKE	FAIR ・ Attn	
PARKING BRAKE	FAIR ・ Attn	
BOOM		
No. of Section	3 SECTIONS	
DERRICKING CYL.	FAIR ・ Attn	
EXTENSION CYL.	FAIR ・ Attn	

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY	
Operator's Seat	FAIR ・ Attn	
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR	

COMMENT

シューパッド剥がれ多数あり MANY RUBBER PADS: PEELED OFF

OUTRIGGERS	X ・ H	
OUTRIGGERS COND.	FAIR ・ Attn	

COMMENT

バケット水平制御シリンダー油漏れあり

BUCKET LEVELING CYLINDER: OIL LEAKING

ポンプ下ホースにじみあり SOME HOSES UNDER PUMP: OIL OOZING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。