

INSPECTION SHEET 検品書
OTHER その他

| | | | | | |
|-----------------|---------------------------------|----------|-------------------|-------------|------|
| INSPECTION DATE | 2026/6/8 | CATEGORY | HAND-GUIDE ROLLER | | |
| MAKE | SAKAI | | MODEL | HV51ST | |
| SERIAL | NO PLATE | | STAMP | 5HV20-20712 | |
| HR METER | UNKNOWN | HR | Odometer | - | km |
| | | | | YEAR | YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP | | NONE | SHOE | TIRE |
| | | | | | - |

| | | |
|-------------|-------------|----------------------------|
| ENGINE | MODEL | S/N |
| Oil leakage | FAIR · Attn | Oil |
| | | FAIR · Attn |
| Blow-By | FAIR · Attn | A LITTLE · MIDDLE · SEVERE |
| | | Exhaust Color |
| | | FAIR · Attn |
| Sound | FAIR · Attn | EPA |
| | | YES · NO |

| | |
|-----------|-------------|
| CONDITION | FAIR · Attn |
| | |

UNDERCARRIAGE : See Photos. 写真参照

| | | | |
|--|---|-----------|---------------------------|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | TIRE WEAR | FAIR · WORN · UNEVEN WEAR |
|--|---|-----------|---------------------------|

COMMENT

.....

.....

.....

.....

.....

.....

.....

.....

.....

| | |
|--|---|
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|--|---|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。