

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/12	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : FD1071		STAMP : TR120-1059		
HR METER	7087	HR	Odometer	73492	km
TIRE SIZE	275/80R22.5		YEAR	2006	YR

ENGINE : MODEL 4M50 S/N

Oil leakage	FAIR	<input checked="" type="radio"/> Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	

TRANSMISSION

Transmission	FAIR	Attn	
No. OF GEARS	3	GEARS	
4WD	<input checked="" type="radio"/> 4WD	<input type="radio"/> 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れ、穴あり CUTS, HOLE
Glasses	FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C	<input type="radio"/> H only · <input type="radio"/> C only · None

COMMENT

--	--

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	Attn	
DERRICKING CYL.	FAIR	Attn	
EXTENSION CYL.	FAIR	Attn	
JIB	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
JIB TYPE	<input checked="" type="radio"/> STD	<input type="radio"/> PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
FREE FALL	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
HOOK	12t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR

COMMENT

右Fタイヤ側面カケあり FRONT RIGHT TIRE SIDEWALL: PARTLY CHIPPED OFF	
---	--

OUTRIGGERS

OUTRIGGERS	X	H	
OUTRIGGERS COND.	FAIR	Attn	
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R

COMMENT

フックインブラケット曲がりあり HOOK-IN BRACKET: A LITTLE DISTORTED	
ロータリー付近油漏れあり AROUND ROTARY: OIL LEAKING	
*1 E/Gヘッドカバー合わせ油漏れあり	
*1 ATTACHING PART OF HEAD COVER: OIL LEAKING	

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。