

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/15	MAKE	HITACHI	MODEL	ZX135USK-3
SERIAL	HCM1R500P00095248		STAMP	HCM1R500P00095248	
HR METER	3195	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL 4JJ1 **S/N** 168405

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	左右サビあり CYLINDERS: RUSTY
Arm	FAIR	Attn	ガタあり LOOSE
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2

COMMENT

左右シューリンク固着あり TRACK LINKS: STUCK

.....
.....
.....

BKT (STD) / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · (WRIST)

Multi MULTI · 2 · (NO)

ARM-CRANE YES · (NO)

BLADE YES · (NO)

OFFSET YES · (NO)

OFFSET Cylinder FAIR · Attn

Piping (YES) · NO Breaker only · (Multi)

COMMENT

リペイントあり REPAINTED

ブーム周りホースひび割れあり

SOME HOSES AROUND BOOM: MUCH CRACKED

.....
.....
.....

.....
.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。