

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2026/6/10	MAKE	KOMATSU	MODEL	D65PX-17
SERIAL	2353		STAMP	KMT0D117L01002353	
HR METER	4952	HR	SHOE	940LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

<b>ENGINE : MODEL</b> 6D114E-5 <b>S/N</b>	
Oil leakage	(FAIR) · Attn
Blow-By	(FAIR) · Attn A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn
Oil	(FAIR) · Attn
Exhaust Color	(FAIR) · Attn
US EPA	(YES) · NO
<b>OPERATION PUMP</b>	
Sound	(FAIR) · Attn
Oil leakage	(FAIR) · Attn
Power	(FAIR) · Attn
<b>COOLING SYSTEM</b>	
Radiator	(FAIR) · Attn
Oil Cooler	(FAIR) · Attn
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE	(PS) · DD DIFF. STEERING (YES) · NO
Transmission	(FAIR) · Attn
Travel	(FAIR) · Attn
<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	(CLEAN) FAIR · DIRTY
Operator's Seat	(FAIR) · Attn 穴あり HOLE
Glasses	(FAIR) · Attn
AirCon	(A/C) · H/C · H only · C only · None
<b>BLADE &amp; CYLINDERS</b>	
BLADE	(FAIR) · Attn
CYLD.(R)	(FAIR) · Attn
CYLD.(L)	(FAIR) · Attn
TILT CYLD	(FAIR) · Attn
ANGLE CYLD	FAIR · Attn

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
<b>COMMENT</b>			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	(FAIR) · Attn		
<b>COMMENT</b>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。