

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/6/10	MAKE	TCM	MODEL	SD23Z6
SERIAL	58102750		STAMP	S15-02750	
HR METER	E3750	HR	Odometer	13613	km
				YEAR	1999
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP		NONE	TIRE SIZE	F: 8.25-20/7.00 R: 7.50-16/6.00

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	フィン腐食あり FINS: CORRODED
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE	<input checked="" type="radio"/> PS · DD	
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn	効き甘い BRAKE: LOOSE
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり CUTS
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
<b>FRONT &amp; CYLINDERS</b>		
Arm	<input checked="" type="radio"/> FAIR · Attn	左右傷あり CYLINDERS: SCRATCHED
Bell crank	<input checked="" type="radio"/> FAIR · Attn	
Bucket	<input checked="" type="radio"/> FAIR · Attn	
Articulate	<input checked="" type="radio"/> FAIR · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR
<b>COMMENT</b>	
ノーパンクタイヤ SOLID TIRES	
下周り油漏れ小 BOTTOM: OIL LEAKING	
STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING	
RIDE CONTROL	YES · <input checked="" type="radio"/> NO
<b>ATTACHMENTS</b>	
STD BKT	<input checked="" type="radio"/> YES · <input type="radio"/> OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>	
マフラー破損あり MUFFLER: BROKEN	
HRメーターストップ HR METER: STOPPED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。