

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|-----------------|----------------|---------|----------|-----------|-----------|
| INSPECTION DATE | 2026/6/9 | MAKE | TADANO | MODEL | GR-500N-2 |
| SERIAL No. | PLATE : 583255 | STAMP : | | T011-0055 | |
| HR METER | 21611 | HR | Odometer | 13997 | km |
| TIRE SIZE | 385/95R25 | YEAR | 2015 | YR | |

| | | |
|----------------------------------|---|----------------------------|
| ENGINE : MODEL | | S/N |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn | |
| Blow-By | <input checked="" type="radio"/> FAIR · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn | |
| Oil | <input checked="" type="radio"/> FAIR · Attn | |
| Exhaust Color | <input checked="" type="radio"/> FAIR · Attn | |
| OPERATION PUMP | | |
| Sound | <input checked="" type="radio"/> FAIR · Attn | |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn | |
| Power | <input checked="" type="radio"/> FAIR · Attn | |
| COOLING SYSTEM | | |
| Radiator | <input checked="" type="radio"/> FAIR · Attn | |
| Oil Cooler | <input checked="" type="radio"/> FAIR · Attn | |
| OPERATING SYSTEM | | |
| Computer | <input checked="" type="radio"/> OK · NG | |
| Swing | <input checked="" type="radio"/> FAIR · Attn | |
| Travel | <input checked="" type="radio"/> FAIR · Attn | |
| TRANSMISSION | | |
| Transmission | <input checked="" type="radio"/> FAIR · Attn | |
| No. OF GEARS | 3 GEARS | |
| 4WD | <input checked="" type="radio"/> 4WD · 6WD | |
| INTERIOR See Photos. 写真参照 | | |
| INTERIOR COND. | CLEAN · <input checked="" type="radio"/> FAIR · DIRTY | |
| Operator's Seat | <input checked="" type="radio"/> FAIR · Attn | |
| Glasses | <input checked="" type="radio"/> FAIR · Attn | |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None | |
| COMMENT | | |
| | | |
| | | |
| | | |

| | | | |
|--|--|-------|------------|
| BOOM | | | |
| No. of Section | 5 SECTIONS | | |
| CRACK/ENFORCEMENT | <input checked="" type="radio"/> FAIR · Attn | | |
| DERRICKING CYL. | <input checked="" type="radio"/> FAIR · Attn | | |
| EXTENSION CYL. | <input checked="" type="radio"/> FAIR · Attn | | |
| JIB | <input checked="" type="radio"/> YES · NO | | |
| JIB TYPE | STD · <input checked="" type="radio"/> PWR | | |
| MAIN & SUB WIRE | <input checked="" type="radio"/> YES · NO | | |
| FREE FALL | YES · <input checked="" type="radio"/> NO | | |
| HOOK | 35t, 25t, BALL | | |
| UNDERCARRIAGE : See Photos. 写真参照 | | | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 1 |
| TIRE WEAR <input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR | | | |
| COMMENT | | | |
| | | | |
| | | | |
| OUTRIGGERS | | | |
| OUTRIGGERS | X · <input checked="" type="radio"/> H | | |
| OUTRIGGERS COND. | <input checked="" type="radio"/> FAIR · Attn | | |
| Oil leakage (JACK CYL.) | FRONT | L · R | REAR L · R |
| Oil leakage (SLIDE CYL.) | FRONT | L · R | REAR L · R |
| COMMENT | | | |
| 穴あり HOLES | | | |
| ER103点灯あり "ER103" ERROR DISPLAY | | | |
| E/Gボンネットカバー欠 ENGINE HOOD: MISSING | | | |
| E/G掛け始め吹けが悪い | | | |
| HARD TO REV UP AT THE BEGGING OF STARTING THE ENGINE | | | |
| | | | |
| | | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 1 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。