

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/12	MAKE	KATO	MODEL	KRM-13HM
SERIAL No.	PLATE :	5912262	STAMP :	KR130-2262	
HR METER	15571	HR	Odometer	105365	km
TIRE SIZE	275/80R22.5	YEAR	2007	YR	

ENGINE : MODEL S/N

Oil leakage	FAIR (Attn)	E/G上部油漏れあり UPPER PART: OIL LEAKING
Blow-By	FAIR (Attn)	A LITTLE · MIDDLE · SEVERE
Sound	FAIR (Attn)	
Oil	FAIR (Attn)	
Exhaust Color	FAIR (Attn)	

OPERATION PUMP

Sound	FAIR (Attn)	
Oil leakage	FAIR (Attn)	
Power	FAIR (Attn)	

COOLING SYSTEM

Radiator	FAIR (Attn)	
Oil Cooler	FAIR (Attn)	

OPERATING SYSTEM

Computer	OK (NG *1)	
Swing	FAIR (Attn)	
Travel	FAIR (Attn)	

TRANSMISSION

Transmission	FAIR (Attn)	
No. OF GEARS	3 GEARS	
4WD	4WD (6WD)	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN (FAIR) DIRTY
Operator's Seat	FAIR (Attn)
Glasses	FAIR (Attn)
AirCon	A/C (H/C · H only · C only · None)

COMMENT

A/C効かない A/C: MALFUNCTION

BOOM

No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	FAIR (Attn)
DERRICKING CYL.	FAIR (Attn)
EXTENSION CYL.	FAIR (Attn)
JIB	YES (NO)
JIB TYPE	STD (PWR)
MAIN & SUB WIRE	YES (NO)
FREE FALL	YES (NO)
HOOK	4.9t, BALL

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR (WORN) UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	X (H) *2
OUTRIGGERS COND.	FAIR (Attn)
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R

COMMENT

ロータリー油漏れあり ROTARY: OIL LEAKING

*1 コンピュータ解除で操作可

*1 NEED TO CUT THE COMPUTER TO OPERATE

*2 アウトリガーストロークセンサー左右F不良

*2 FRONT OUTRIGGER EXTENSION SENSORS: MALFUNCTION

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。