# INSPECTION SHEET 検品書

## CARRY DUMP キャリーダンプ

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2026/6/11 | MAKE | MOROOKA | MODEL | MST-2200VDR |
| SERIAL | 044423 | | | STAMP | 044423 |
| HR METER | 5335 / 5311 HR | Odometer | km | YEAR | YR |
| CAB/CNP | (ROPS CAB) / CAB / ROPS CNP / CNP / NONE | | | SHOE | 800R |
| TIRE | | | | | |

| | | |
|---|---|---|
| **ENGINE : MODEL** | C7.1 | **S/N** |
| Oil leakage | (FAIR) · Attn | |
| Blow-By | (FAIR) · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | (FAIR) · Attn | |
| Oil | (FAIR) · Attn | |
| Exhaust Color | (FAIR) · Attn | |
| US EPA | (YES) · NO | |
| **OPERATION PUMP** | | |
| Sound | (FAIR) · Attn | |
| Oil leakage | (FAIR) · Attn | |
| Power | (FAIR) · Attn | |
| **COOLING SYSTEM** | | |
| Radiator | (FAIR) · Attn | |
| Oil Cooler | (FAIR) · Attn | |
| **TRANSMISSION & TRAVEL** | | |
| T/M TYPE | (PS) · DD | No. OF GEARS 2 GEARS |
| Transmission | (FAIR) · Attn | |
| Travel | (FAIR) · Attn | |
| Swing | (FAIR) · Attn | |
| Articulate | FAIR · Attn | |
| FOOT BRAKE | FAIR · Attn | |
| PARKING BRAKE | (FAIR) · Attn | |
| **INTERIOR** | **See Photos. 写真参照** | |
| INTERIOR COND. | (CLEAN) · FAIR · DIRTY | |
| Operator's Seat | (FAIR) · Attn | |
| Glasses | (FAIR) · Attn | |
| AirCon | (A/C) · H/C · H only · C only · None | |

| | | |
|---|---|---|
| **MAIN FRAME** | | |
| MAIN FLAME | (FAIR) · Attn | |
| **VESSEL** | | |
| VESSEL | (FAIR) · Attn | |
| REAR GATE TYPE | NORMAL · L-GATE (FLAT) | |
| REAR GATE | FAIR · Attn | |
| **UNDERCARRIAGE:** | **See Photos. 写真参照** | |
| **RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | 4 |
| TIRE WEAR | FAIR · WORN · UNEVEN WEAR | |

**COMMENT**

キーでE/Gストップ効かない(エマージェンシーS/WでOFF)

UNABLE TO STOP THE ENGINE BY IGNITION KEY

(ABLE TO STOP THE ENGINE

BY TURN OFF THE EMERGENCY SWITCH)

| | |
|---|---|
| **RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。