

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|-----------------|-----------|--------|----------|-----------|-----------|
| INSPECTION DATE | 2026/6/4 | MAKE | TADANO | MODEL | GR-500N-2 |
| SERIAL No. | PLATE : | 583262 | STAMP : | T011-0062 | |
| HR METER | 15610 | HR | Odometer | 47477 | km |
| TIRE SIZE | 385/95R25 | | YEAR | YR | |

| ENGINE : MODEL | S/N |
|----------------------------------|---|
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Blow-By | <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil | <input checked="" type="radio"/> FAIR · Attn |
| Exhaust Color | <input checked="" type="radio"/> FAIR · Attn |
| OPERATION PUMP | |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Power | <input checked="" type="radio"/> FAIR · Attn |
| COOLING SYSTEM | |
| Radiator | <input checked="" type="radio"/> FAIR · Attn |
| Oil Cooler | <input checked="" type="radio"/> FAIR · Attn |
| OPERATING SYSTEM | |
| Computer | <input checked="" type="radio"/> OK · NG |
| Swing | <input checked="" type="radio"/> FAIR · Attn |
| Travel | <input checked="" type="radio"/> FAIR · Attn |
| TRANSMISSION | |
| Transmission | <input checked="" type="radio"/> FAIR · Attn |
| No. OF GEARS | 4 GEARS |
| 4WD | <input checked="" type="radio"/> 4WD · 6WD |
| INTERIOR See Photos. 写真参照 | |
| INTERIOR COND. | CLEAN · <input checked="" type="radio"/> FAIR · DIRTY |
| Operator's Seat | <input checked="" type="radio"/> FAIR · Attn 破れ小 CUT |
| Glasses | <input checked="" type="radio"/> FAIR · Attn |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |
| COMMENT | |
| | |

| BOOM | |
|--|--|
| No. of Section | 5 SECTIONS |
| CRACK/ENFORCEMENT | <input checked="" type="radio"/> FAIR · Attn |
| DERRICKING CYL. | <input checked="" type="radio"/> FAIR · Attn |
| EXTENSION CYL. | <input checked="" type="radio"/> FAIR · Attn |
| JIB | <input checked="" type="radio"/> YES · NO |
| JIB TYPE | STD · <input checked="" type="radio"/> PWR |
| MAIN & SUB WIRE | <input checked="" type="radio"/> YES · NO |
| FREE FALL | YES · <input checked="" type="radio"/> NO |
| HOOK | 35t, 25t, BALL |
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2 |
| TIRE WEAR | FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR |
| COMMENT | |
| | |
| OUTRIGGERS | |
| OUTRIGGERS | X · <input checked="" type="radio"/> H |
| OUTRIGGERS COND. | <input checked="" type="radio"/> FAIR · Attn |
| Oil leakage (JACK CYL.) | FRONT L · R REAR L · R |
| Oil leakage (SLIDE CYL.) | FRONT L · R REAR L · R |
| COMMENT | |
| 作動油タンク下油漏れあり BOTTOM OF HYDRAULIC OIL TANK: OIL LEAKING | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 1 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。