

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|-----------------|----------------|---------|----------|-----------|---------|
| INSPECTION DATE | 2026/6/9 | MAKE | KOBELCO | MODEL | RK700-2 |
| SERIAL No. | PLATE : FY0016 | STAMP : | | T008-5016 | |
| HR METER | 10038 | HR | Odometer | 30068 | km |
| TIRE SIZE | 385/95R25 | YEAR | YR | | |

| | | |
|---------------------------------------------------|---------------------------------------------------------------------|----------------------------|
| ENGINE : MODEL | | S/N |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn | |
| Blow-By | <input checked="" type="radio"/> FAIR · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn | |
| Oil | <input checked="" type="radio"/> FAIR · Attn | |
| Exhaust Color | <input checked="" type="radio"/> FAIR · Attn | |
| OPERATION PUMP | | |
| Sound | <input checked="" type="radio"/> FAIR · Attn | |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn | |
| Power | <input checked="" type="radio"/> FAIR · Attn | |
| COOLING SYSTEM | | |
| Radiator | <input checked="" type="radio"/> FAIR · Attn | |
| Oil Cooler | <input checked="" type="radio"/> FAIR · Attn | |
| OPERATING SYSTEM | | |
| Computer | <input checked="" type="radio"/> OK · NG | |
| Swing | <input checked="" type="radio"/> FAIR · Attn | |
| Travel | <input checked="" type="radio"/> FAIR · Attn | |
| TRANSMISSION | | |
| Transmission | <input checked="" type="radio"/> FAIR · Attn | |
| No. OF GEARS | 3 GEARS | |
| 4WD | <input checked="" type="radio"/> 4WD · 6WD | |
| INTERIOR See Photos. 写真参照 | | |
| INTERIOR COND. | CLEAN · <input checked="" type="radio"/> FAIR · DIRTY | |
| Operator's Seat | <input checked="" type="radio"/> FAIR · Attn | |
| Glasses | <input checked="" type="radio"/> FAIR · Attn | |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None | |
| COMMENT | | |
| 運転席右ミラー割れあり RIGHT OUTER REAR-VIEW MIRROR: CRACKED | | |

| | | | |
|----------------------------------------------------------------------|---------------------------------------------------------------------------------------------|----------|------------|
| BOOM | | | |
| No. of Section | 6 | SECTIONS | |
| CRACK/ENFORCEMENT | <input checked="" type="radio"/> FAIR · Attn | | |
| DERRICKING CYL. | <input checked="" type="radio"/> FAIR · Attn | | |
| EXTENSION CYL. | <input checked="" type="radio"/> FAIR · Attn | | |
| JIB | <input checked="" type="radio"/> YES · NO | | |
| JIB TYPE | STD · <input checked="" type="radio"/> PWR | | |
| MAIN & SUB WIRE | <input checked="" type="radio"/> YES · NO | | |
| FREE FALL | YES · <input checked="" type="radio"/> NO | | |
| HOOK | 35t × 2, BALL, SHEAVE × 2 | | |
| UNDERCARRIAGE : See Photos. 写真参照 | | | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 3 |
| TIRE WEAR | <input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR | | |
| COMMENT | | | |
| | | | |
| OUTRIGGERS | | | |
| OUTRIGGERS | X · <input checked="" type="radio"/> H | | |
| OUTRIGGERS COND. | <input checked="" type="radio"/> FAIR · Attn | | |
| Oil leakage (JACK CYL.) | FRONT | L · R | REAR L · R |
| Oil leakage (SLIDE CYL.) | FRONT | L · R | REAR L · R |
| COMMENT | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。