

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/15	MAKE	TADANO	MODEL	GR-700N-1
SERIAL No.	PLATE : FE0842		STAMP : T008-0356		
HR METER	9431	HR	Odometer	27563	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	

OPERATION PUMP

Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	

COOLING SYSTEM

Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	

OPERATING SYSTEM

Computer	<input checked="" type="radio"/> OK	NG	
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	

TRANSMISSION

Transmission	<input checked="" type="radio"/> FAIR	Attn	
No. OF GEARS	3	GEARS	
4WD	4WD	<input checked="" type="radio"/> 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	<input checked="" type="radio"/> FAIR	DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR	Attn	
DERRICKING CYL.	<input checked="" type="radio"/> FAIR	Attn	
EXTENSION CYL.	<input checked="" type="radio"/> FAIR	Attn	
JIB	<input checked="" type="radio"/> YES	NO	
JIB TYPE	STD	<input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> YES	NO	
FREE FALL	YES	<input checked="" type="radio"/> NO	
HOOK	35t × 2, BALL, HANGER × 2		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	X	<input checked="" type="radio"/> H	
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R

COMMENT

エアクリーナーケース損傷あり AIR CLEANER CASE: DAMAGED	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。