

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/15	MAKE	KOBELCO	MODEL	RK500
SERIAL No.	PLATE : ET05-05166		STAMP : ET03-5166		
HR METER	32061	HR	Odometer	109485	km
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	<input type="radio"/> FAIR · Attn
Blow-By	<input type="radio"/> FAIR · <input checked="" type="radio"/> A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn
Oil	<input type="radio"/> FAIR · Attn
Exhaust Color	<input type="radio"/> FAIR · <input checked="" type="radio"/> 白煙あり WHITE FUMES

OPERATION PUMP

Sound	<input type="radio"/> FAIR · Attn
Oil leakage	<input type="radio"/> FAIR · Attn
Power	<input type="radio"/> FAIR · Attn

COOLING SYSTEM

Radiator	<input type="radio"/> FAIR · Attn
Oil Cooler	<input type="radio"/> FAIR · Attn

OPERATING SYSTEM

Computer	<input checked="" type="radio"/> OK · NG
Swing	<input type="radio"/> FAIR · Attn
Travel	<input type="radio"/> FAIR · Attn

TRANSMISSION

Transmission	<input type="radio"/> FAIR · Attn
No. OF GEARS	3 GEARS
4WD	<input checked="" type="radio"/> 4WD · 6WD

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input type="radio"/> FAIR · Attn 破れあり HUGE CUT
Glasses	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn Fガラスひび割れあり WINDSHIELD: CRACKED
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None

COMMENT

CABへゴミあり LOWER PART OF CAB: DENT

BOOM

No. of Section	5 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · Attn
DERRICKING CYL.	<input type="radio"/> FAIR · Attn
EXTENSION CYL.	<input type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
FREE FALL	<input checked="" type="radio"/> YES · NO
HOOK	51t, 25t, BALL

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	<input type="radio"/> FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR

COMMENT

右ハブシール油漏れあり REAR RIGHT HUB SEAL: OIL LEAKING
燃料タンク横カバーへゴミあり RIGHT SIDE FENDER: DENT

OUTRIGGERS

OUTRIGGERS	<input checked="" type="radio"/> X · H
OUTRIGGERS COND.	<input type="radio"/> FAIR · Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R

COMMENT

ロータリー下ホース付近油漏れあり	
MANY HOSES UNDER ROTARY: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。