

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/11	MAKE	HITACHI	MODEL	ZX240LCMH-5B
SERIAL	HCMDCAA6H00030727		STAMP	HCMDCAA6H00030727	
HR METER	12572	HR	YEAR	2018	YR
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	600FLAT	

ENGINE : MODEL 4HK1 S/N 765831	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	YES · <u>NO</u>
MAIN PUMP	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · <u>Attn</u> 油漏れあり OIL LEAKING
Power	<u>FAIR</u> · Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
OPERATING SYSTEM	
Swing	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY
Operator's Seat	<u>FAIR</u> · Attn
Glasses	<u>FAIR</u> · Attn
AirCon	<u>A/C</u> · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	<u>FAIR</u> · Attn *1
Boom Cylinder	<u>FAIR</u> · <u>Attn</u> 右側油漏れ小 RIGHT CYLINDER: OIL LEAKING
Arm	<u>FAIR</u> · <u>Attn</u> *2
Arm Cylinder	<u>FAIR</u> · Attn
ATTACHMENT	<u>FAIR</u> · Attn
BKT Cylinder	<u>FAIR</u> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	<u>YES</u> · NO Breaker only · Multi 5
COMMENT	
リペイントあり REPAINTED	
E/G異常警告あり ENGINE WARNING DISPLAY	
エレベータCAB ELEVATOR CAB	
バックカメラ不良(検品時は映っていた)	
BACK MONITOR: MALFUNCTION	
(JUST CHECKED TO DISPLAY AT THE INSPECTION TIME)	
アタッチメントなし WITHOUT ATTACHMENT	
付属品: チューリップバケット	
ORANGE PEEL GRAPPLE AS SPARE (MAKE: MATSUMOTO TRG-2200)	
*1 ストレートブーム STRAIGHT BOOM (LENGTH: 10.85m)	
*2 アーム動作レバー倒してから1秒後くらいに動く ARM: DULL MOVING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。