

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/6/11	MAKE	KOMATSU	MODEL	D31PLL-20E
SERIAL	49196		STAMP	49196	
HR METER	8811	HR	SHOE	1050LGP	YEAR YR
BLADE	STRAIGHT / <u>ST/TILT</u> / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">ENGINE : MODEL</td> <td style="width: 70%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>Blow-By</td> <td><u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>Oil</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>Exhaust Color</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>US EPA</td> <td><u>YES</u> · NO</td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>Oil leakage</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>Power</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>Oil Cooler</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td><u>PS</u> · DD DIFF. STEERING YES · <u>NO</u></td> </tr> <tr> <td>Transmission</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>Travel</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · <u>FAIR</u> · DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>Glasses</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>AirCon</td> <td><u>A/C</u> · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>CYLD.(R)</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>CYLD.(L)</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>TILT CYLD</td> <td><u>FAIR</u> · Attn</td> </tr> <tr> <td>ANGLE CYLD</td> <td>FAIR · Attn</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	<u>FAIR</u> · Attn	Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE	Sound	<u>FAIR</u> · Attn	Oil	<u>FAIR</u> · Attn	Exhaust Color	<u>FAIR</u> · Attn	US EPA	<u>YES</u> · NO	OPERATION PUMP		Sound	<u>FAIR</u> · Attn	Oil leakage	<u>FAIR</u> · Attn	Power	<u>FAIR</u> · Attn	COOLING SYSTEM		Radiator	<u>FAIR</u> · Attn	Oil Cooler	<u>FAIR</u> · Attn	TRANSMISSION & TRAVEL		T/M TYPE	<u>PS</u> · DD DIFF. STEERING YES · <u>NO</u>	Transmission	<u>FAIR</u> · Attn	Travel	<u>FAIR</u> · Attn	INTERIOR See Photos. 写真参照		INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	Operator's Seat	<u>FAIR</u> · Attn	Glasses	<u>FAIR</u> · Attn	AirCon	<u>A/C</u> · H/C · H only · C only · None	BLADE & CYLINDERS		BLADE	<u>FAIR</u> · Attn	CYLD.(R)	<u>FAIR</u> · Attn	CYLD.(L)	<u>FAIR</u> · Attn	TILT CYLD	<u>FAIR</u> · Attn	ANGLE CYLD	FAIR · Attn	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">3</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>Ripper MULTI · S/S Shanks PCS</p> <p>Ripper CYLD. FAIR · Attn</p> </div> <div style="width: 45%;"> <p>COMMENT</p> <p>コントロールバルブにじみあり CONTROL VALVE: OIL OOZING トラッカー受光機欠、コントロールボックス電源入らない SPECTRA PRECISION SYSTEM (RECEIVER: MISSING, CONTROL BOX: UNABLE TO TURN ON) A/Cベルト欠、コンプレッサー固着気味 A/C: NO BELT, COMPRESSOR: A LITTLE STUCK</p> </div> </div> </td> </tr> <tr> <td>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">3</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	COMMENT		<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>Ripper MULTI · S/S Shanks PCS</p> <p>Ripper CYLD. FAIR · Attn</p> </div> <div style="width: 45%;"> <p>COMMENT</p> <p>コントロールバルブにじみあり CONTROL VALVE: OIL OOZING トラッカー受光機欠、コントロールボックス電源入らない SPECTRA PRECISION SYSTEM (RECEIVER: MISSING, CONTROL BOX: UNABLE TO TURN ON) A/Cベルト欠、コンプレッサー固着気味 A/C: NO BELT, COMPRESSOR: A LITTLE STUCK</p> </div> </div>		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
ENGINE : MODEL	S/N																																																																				
Oil leakage	<u>FAIR</u> · Attn																																																																				
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE																																																																				
Sound	<u>FAIR</u> · Attn																																																																				
Oil	<u>FAIR</u> · Attn																																																																				
Exhaust Color	<u>FAIR</u> · Attn																																																																				
US EPA	<u>YES</u> · NO																																																																				
OPERATION PUMP																																																																					
Sound	<u>FAIR</u> · Attn																																																																				
Oil leakage	<u>FAIR</u> · Attn																																																																				
Power	<u>FAIR</u> · Attn																																																																				
COOLING SYSTEM																																																																					
Radiator	<u>FAIR</u> · Attn																																																																				
Oil Cooler	<u>FAIR</u> · Attn																																																																				
TRANSMISSION & TRAVEL																																																																					
T/M TYPE	<u>PS</u> · DD DIFF. STEERING YES · <u>NO</u>																																																																				
Transmission	<u>FAIR</u> · Attn																																																																				
Travel	<u>FAIR</u> · Attn																																																																				
INTERIOR See Photos. 写真参照																																																																					
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY																																																																				
Operator's Seat	<u>FAIR</u> · Attn																																																																				
Glasses	<u>FAIR</u> · Attn																																																																				
AirCon	<u>A/C</u> · H/C · H only · C only · None																																																																				
BLADE & CYLINDERS																																																																					
BLADE	<u>FAIR</u> · Attn																																																																				
CYLD.(R)	<u>FAIR</u> · Attn																																																																				
CYLD.(L)	<u>FAIR</u> · Attn																																																																				
TILT CYLD	<u>FAIR</u> · Attn																																																																				
ANGLE CYLD	FAIR · Attn																																																																				
UNDERCARRIAGE See Photos. 写真参照																																																																					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																				
COMMENT																																																																					
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>Ripper MULTI · S/S Shanks PCS</p> <p>Ripper CYLD. FAIR · Attn</p> </div> <div style="width: 45%;"> <p>COMMENT</p> <p>コントロールバルブにじみあり CONTROL VALVE: OIL OOZING トラッカー受光機欠、コントロールボックス電源入らない SPECTRA PRECISION SYSTEM (RECEIVER: MISSING, CONTROL BOX: UNABLE TO TURN ON) A/Cベルト欠、コンプレッサー固着気味 A/C: NO BELT, COMPRESSOR: A LITTLE STUCK</p> </div> </div>																																																																					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。