

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |  |      |         |                   |           |
|-----------------|--|------|---------|-------------------|-----------|
| INSPECTION DATE | 2026/6/1                               | MAKE | KOMATSU | MODEL             | PC138US-8 |
| SERIAL          | 29532                                  |      | STAMP   | KMTPC189H01029532 |           |
| HR METER        | 3305                                   | HR   | YEAR    | YR                |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 500G              |           |

**ENGINE : MODEL** 4D95LE-5 **S/N** 534929

|               |      |      |                            |
|---------------|------|------|----------------------------|
| Oil leakage   | FAIR | Attn |                            |
| Blow-By       | FAIR | Attn | A LITTLE · MIDDLE · SEVERE |
| Sound         | FAIR | Attn |                            |
| Oil           | FAIR | Attn |                            |
| Exhaust Color | FAIR | Attn |                            |
| US EPA        | YES  | NO   |                            |

**MAIN PUMP**

|             |      |      |  |
|-------------|------|------|--|
| Sound       | FAIR | Attn |  |
| Oil leakage | FAIR | Attn |  |
| Power       | FAIR | Attn |  |

**COOLING SYSTEM**

|            |      |      |  |
|------------|------|------|--|
| Radiator   | FAIR | Attn |  |
| Oil Cooler | FAIR | Attn |  |

**OPERATING SYSTEM**

|        |      |      |  |
|--------|------|------|--|
| Swing  | FAIR | Attn |  |
| Travel | FAIR | Attn |  |

**INTERIOR** See Photos. 写真参照

|                 |       |      |                        |
|-----------------|-------|------|------------------------|
| INTERIOR COND.  | CLEAN | FAIR | DIRTY                  |
| Operator's Seat | FAIR  | Attn |                        |
| Glasses         | FAIR  | Attn |                        |
| AirCon          | A/C   | H/C  | H only · C only · None |

**BOOM / ARM / BKT**

|               |      |      |                                |
|---------------|------|------|--------------------------------|
| Boom          | FAIR | Attn | クラックあり CRACKED                 |
| Boom Cylinder | FAIR | Attn | 両側油漏れあり CYLINDERS: OIL LEAKING |
| Arm           | FAIR | Attn | ガタあり LOOSE                     |
| Arm Cylinder  | FAIR | Attn |                                |
| ATTACHMENT    | FAIR | Attn |                                |
| BKT Cylinder  | FAIR | Attn |                                |

**UNDERCARRIAGE :** See Photos. 写真参照

|  |   |
|--|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3   |
| <b>COMMENT</b>   |   |
| 両側ピンブッシュ割れあり SOME PIN BUSHES: BROKEN                         |   |
|  |   |
| BKT  | STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever  | LONG · WRIST                                |
| Multi  | MULTI · 2 · NO                              |
| ARM-CRANE  | YES · NO                                    |
| BLADE  | YES · NO                                    |
| OFFSET   | YES · NO                                    |
| OFFSET Cylinder  | FAIR · Attn                                 |
| Piping   | YES · NO Breaker only · Multi               |

**COMMENT**

Iリンク、Hリンクガタあり I-LINKS & H-LINK: LOOSE  
A/Cエラー表示あり A/C ERROR DISPLAY  
ファンベルト鳴きあり FAN BELT: NOISES

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。