

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/6/12	MAKE	KOMATSU	MODEL	D31-16
SERIAL	29019		STAMP	D3116-29019	
HR METER	E2619	HR	SHOE	400G	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	DIFF. STEERING YES · NO
Transmission	FAIR · Attn	
Travel	FAIR · Attn	*1
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BLADE & CYLINDERS		
BLADE	FAIR · Attn	
CYLD.(R)	FAIR · Attn	ホースひび割れあり HOSES: CRACKED
CYLD.(L)	FAIR · Attn	ホースひび割れあり HOSES: CRACKED
TILT CYLD	FAIR · Attn	ホースひび割れあり HOSES: CRACKED
ANGLE CYLD	FAIR · Attn	*2

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
Ripper MULTI · S/S Shanks PCS			
Ripper CYLD.	FAIR · Attn		
COMMENT			
コントロールバルブにじみあり CONTROL VALVE: OIL OOZING			
HRメーターストップ HR METER: STOPPED			
ウインチ付(レバー固着あり、動作不可)			
W/WINCH (LEVER: STUCK, UNABLE TO OPERATE)			
*1 左右レバー固着気味 TRAVEL LEVERS: A LITTLE STUCK			
*2 ホースひび割れ、右シリンダーにじみあり、			
左側シリンダー油漏れ小、サビあり			
*2 HOSES: CRACKED, RIGHT CYLINDER: OIL OOZING,			
LEFT CYLINDER: OIL LEAKING, RUSTY			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。