INSPECTION SHEET 検品書
ASPHALT FINISHER　アスファルトフィニッシャー

INSPECTION DATE	2026/6/9	MAKE	MITSUBISHI	MODEL	MF31WD
SERIAL	A8H07203		STAMP	A8H107203	
HR METER	4525 HR		YEAR	YR	
SHOE		TIRE (REAR)	13.5-20	MAX PAVING WIDTH	3100 mm

ENGINE : MODEL	S/N	
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
TRAVEL	(FAIR)・ Attn	
SCREED(R)	(FAIR)・ Attn	
SCREED(L)	(FAIR)・ Attn	
VIBRATION	(FAIR)・ Attn	
TAMPER	FAIR ・ Attn	
SPREADER(R)	(FAIR)・ Attn	
SPREADER(L)	(FAIR)・ Attn	
HOPPER(R)	(FAIR)・ Attn	
HOPPER(L)	FAIR ・(Attn)	CYLINDER: OIL OOZING
FEEDER	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	(FAIR ・)WORN ・ UNEVEN WEAR	
COMMENT		

SCREED WIDTH		
MAIN SCREED	1.8	m
WITH AUTO-WIDENER	3.1	m
WITH EXTENSION		m
LEVEL SENSOR	YES ・(NO)	

COMMENT

パーキング効かない　PARKING BRAKE: MALFUNCTION

シート破れあり　SEAT: A LITTLE TORN

*1 ヘッド周り油漏れ小　AROUND CYLINDER HEAD: OIL LEAKING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。