

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/6/16	MAKE	NICHIGO	MODEL	HTR-141
SERIAL	HTR140-319			STAMP	HTR140-319
HR METER	5151	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB	ROPS CNP / CNP / NONE	TIRE SIZE	8.25-20 14PR (SNOW, SPIKE)	

ENGINE : MODEL	6BD1	S/N	588604
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	*1
Power	FAIR · Attn	

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	*2

INTERIOR	See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れ、穴あり HUGE CUTS, HOLES
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

FRONT & CYLINDERS		
Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE :	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR	WORN · UNEVEN WEAR

COMMENT	
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	YES	NO
--------------	-----	----

ATTACHMENTS			
STD BKT	YES	OTHER	ロータリー ROTARY SNOWPLOW
BLADE	YES	NO	Piping for Tilt YES NO

COMMENT	
タコメーター TACHOMETER: 7662km	
下周り油漏れあり BOTTOM: OIL LEAKING	
*1 ポンプ周り油漏れあり(吸着マット付)	
*1 AROUND PUMP: OIL LEAKING (W/ABSORPTION MAT)	
*2 プブレーキ解除した際にレバー戻りあり(レバー抑えながら走行可能)	
*2 PARKING BRAKE LEVER:	
RETURN TO THE LOCKED POSITION AFTER RELEASING THE BRAKE	
(ABLE TO TRAVEL BY HOLDING THE LEVER	
AT THE UNLOCKED POSITION)	
</	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。