

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |  |      |         |                   |          |
|-----------------|--|------|---------|-------------------|----------|
| INSPECTION DATE | 2026/6/9                               | MAKE | KOMATSU | MODEL             | PC78US-8 |
| SERIAL          | 28520                                  |      | STAMP   | KMTPC213TEA028520 |          |
| HR METER        | 4708                                   | HR   | YEAR    | YR                |          |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 450G PADS         |          |

**ENGINE : MODEL** 4D95LE-5 **S/N** 557375

|               |      |      |                            |
|---------------|------|------|----------------------------|
| Oil leakage   | FAIR | Attn |                            |
| Blow-By       | FAIR | Attn | A LITTLE · MIDDLE · SEVERE |
| Sound         | FAIR | Attn |                            |
| Oil           | FAIR | Attn |                            |
| Exhaust Color | FAIR | Attn |                            |
| US EPA        | YES  | NO   |                            |

**MAIN PUMP**

|             |      |      |  |
|-------------|------|------|--|
| Sound       | FAIR | Attn |  |
| Oil leakage | FAIR | Attn |  |
| Power       | FAIR | Attn |  |

**COOLING SYSTEM**

|            |      |      |  |
|------------|------|------|--|
| Radiator   | FAIR | Attn |  |
| Oil Cooler | FAIR | Attn |  |

**OPERATING SYSTEM**

|        |      |      |                  |
|--------|------|------|------------------|
| Swing  | FAIR | Attn | ガタ小 SWING: LOOSE |
| Travel | FAIR | Attn |                  |

**INTERIOR See Photos. 写真参照**

|                 |       |      |                        |
|-----------------|-------|------|------------------------|
| INTERIOR COND.  | CLEAN | FAIR | DIRTY                  |
| Operator's Seat | FAIR  | Attn |                        |
| Glasses         | FAIR  | Attn |                        |
| AirCon          | A/C   | H/C  | H only · C only · None |

**BOOM / ARM / BKT**

|               |      |      |  |
|---------------|------|------|--|
| Boom          | FAIR | Attn |  |
| Boom Cylinder | FAIR | Attn |  |
| Arm           | FAIR | Attn |  |
| Arm Cylinder  | FAIR | Attn |  |
| ATTACHMENT    | FAIR | Attn |  |
| BKT Cylinder  | FAIR | Attn |  |

**UNDERCARRIAGE : See Photos. 写真参照**

**RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)** 3

**COMMENT**

.....  
 .....  
 .....  
 .....

**BKT** (STD) / SLOPE / NARROW / SKELETON / OTHER ( )

**Lever** LONG · (WRIST)

**Multi** (MULTI) · 2 · NO

**ARM-CRANE** YES · (NO)

**BLADE** (YES) · NO

**OFFSET** YES · (NO)

**OFFSET Cylinder** FAIR · Attn

**Piping** (YES) · NO (Breaker only) · Multi

**COMMENT**

.....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....

**RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)** 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。