INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/10	MAKE	KOBELCO	MODEL	SK210LC
SERIAL	YQ09-05278			STAMP	YQ09-05278
HR METER	11013 HR			YEAR	YR
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 6D34 S/N		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	FAIR ・(Attn)	油漏れあり OIL LEAKING
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	FAIR ・(Attn)	配管油漏れ小 SOME PIPE: OIL LEAKING
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	FAIR ・(Attn)	フレーム露出あり A LITTLE DAMAGED
Glasses	(FAIR)・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	FAIR ・(Attn)	*2
Boom Cylinder	FAIR ・(Attn)	左右傷あり CYLINDERS: SCRATCHED
Arm	FAIR ・(Attn)	パッチあり、ガタ大 PATCHED, MUCH LOOSE
Arm Cylinder	(FAIR)・ Attn	
ATTACHMENT	(FAIR)・ Attn	
BKT Cylinder	FAIR ・(Attn)	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD / (SLOPE) / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	(MULTI)・ 2 ・ NO	
ARM-CRANE	YES ・(NO)	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	(YES)・ NO	Breaker only ・ (Multi)
COMMENT		

コモンレール燃料漏れあり COMMON RAIL: FUEL LEAKING
ブーム背面旋回モーター周りホースひび割れあり
SOME HOSE AROUND LOWER PART OF BOOM: CRACKED
コントロールバルブにじみあり CONTROL VALVE: OIL OOZING
「E/Gオイルをかえてください」表示あり
WARNING DISPLAY FOR ENGINE OIL REPLACEMENT
*1 ヘッド周りにじみあり AROUND CYLINDER HEAD: OIL OOZING
*2 パッチあり、ストレートブーム
*2 PATCHED, STRAIGHT BOOM (LENGTH: 12.8m)

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。