

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/15	MAKE	HITACHI	MODEL	EX200-2
SERIAL	147-72465		STAMP	147-72465	
HR METER	17498	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油漏れ小、カバー欠 OIL LEAKING, COVER: MISSING
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	オイル混入あり OIL: MIXED
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	*1
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	パッチあり PATCHED
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER / FORK GRAB
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi *2
COMMENT	
底板油汚れあり BOTTOM: OIL STAINS	
ブーム旋回モーター周りホースひび割れ多数あり	
SOME HOSES AROUND BOOM SWING MOTOR: A LITTLE DAMAGED	
燃料配管にじみあり FUEL PIPE: OIL OOZING	
ヒーターベルト欠 HEATER: NO BELT	
*1 左右レバー放しても5cmくらい動く(走行モーターのガタ?)	
*1 CONTINUING TO TRAVEL FOR 5cm	
AFTER OPERATING TRAVEL LEVERS	
(TRAVEL MOTORS: LOOSE?)	
*2 左側ホース、配管欠 LEFT HOSE & PIPE: PARTLY MISSING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。