INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2026/6/12	CATEGORY	ON-ROAD DUMP ・ (OFF-ROAD DUMP)
MAKE	KOMATSU	MODEL	HM300-5
SERIAL	11085	STAMP	11085
HR METER	5712 HR	ODOMETER	33291 km
TIRE SIZE	30/65R25	YEAR	YR

ENGINE : MODEL 6D125E-7 S/N 866874		
Oil leakage	(FAIR) ・ Attn	
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	
COOLING SYSTEM		
Radiator	(FAIR) ・ Attn	
Oil Cooler	(FAIR) ・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(AT) ・ MT	No. OF GEARS 5 GEARS
Transmission	(FAIR) ・ Attn	
4WD	4WD ・(2WD)	
Travel	(FAIR) ・ Attn	
Articulate	(FAIR) ・ Attn	
FOOT BRAKE	(FAIR) ・ Attn	
PARKING BRAKE	(FAIR) ・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR) ・ Attn	
Glasses	(FAIR) ・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	

MAIN FRAME		
MAIN FLAME	(FAIR) ・ Attn	
VESSEL		
MAKE		
VESSEL	(FAIR) ・ Attn	
REAR GATE TYPE	NORMAL ・ L-GATE (FLAT)	
REAR GATE	FAIR ・ Attn	
UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR ・ WORN ・ (UNEVEN WEAR)	

COMMENT

ROPS-CAB

AdBlue噴射系統異常表示あり

WARNING DISPLAY FOR AdBlue INJECTION SYSTEM

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。