

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2026/6/11	MAKE	CAT	MODEL	PF-290B
SERIAL	1XW00058			STAMP	1XW00058
HR METER	UNKNOWN	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE			TIRE SIZE	14/70-20

ENGINE : MODEL 3054 S/N 5HK63672	UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage <u>FAIR</u> · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
Blow-By <u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE	TIRE WEAR <u>FAIR</u> · WORN · UNEVEN WEAR	
Sound <u>FAIR</u> · Attn	COMMENT 右Fタイヤ近くポンプ周り水漏れあり AROUND PUMP NEXT TO FRONT RIGHT TIRE: WATER LEAKING 左右Rモーター油漏れあり REAR MOTORS: OIL LEAKING 燃料フィルター漏れあり FUEL FILTER: FUEL LEAKING	
Oil <u>FAIR</u> · Attn		
Exhaust Color <u>FAIR</u> · Attn		
US EPA YES · <u>NO</u>		
OPERATION PUMP		
Sound <u>FAIR</u> · Attn		
Oil leakage <u>FAIR</u> · Attn		
Power <u>FAIR</u> · Attn		
COOLING SYSTEM		
Radiator <u>FAIR</u> · Attn		
Oil Cooler <u>FAIR</u> · Attn		
TRANSMISSION & TRAVEL		
T/M TYPE <u>PS</u> · DD		
Transmission <u>FAIR</u> · Attn		
Travel <u>FAIR</u> · Attn		
FOOT BRAKE <u>FAIR</u> · Attn		
PARKING BRAKE <u>FAIR</u> · Attn		
INTERIOR See Photos. 写真参照		
INTERIOR COND. CLEAN · <u>FAIR</u> · DIRTY		
Operator's Seat <u>FAIR</u> · Attn 破れあり HUGE CUTS		
Glasses FAIR · Attn		
AirCon A/C · H/C · H only · C only · <u>None</u>		
OTHERS		
Vibratory FAIR · Attn		
Watering FAIR · <u>Attn</u> 散水不良 MALFUNCTION TO WATER		
Articulate FAIR · Attn	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。