

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/8	MAKE	CAT	MODEL	303ECR
SERIAL	CAT0303EJSMG01519			STAMP	CAT0303EJSMG01519
HR METER	4993	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE			SHOE	300G PADS

ENGINE : MODEL C1.3 S/N 1GL2651	
Oil leakage	<u>FAIR</u> • Attn
Blow-By	<u>FAIR</u> • Attn A LITTLE • MIDDLE • SEVERE
Sound	<u>FAIR</u> • Attn
Oil	<u>FAIR</u> • Attn
Exhaust Color	<u>FAIR</u> • Attn
US EPA	<u>YES</u> • NO
MAIN PUMP	
Sound	<u>FAIR</u> • Attn
Oil leakage	<u>FAIR</u> • Attn
Power	<u>FAIR</u> • Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> • Attn
Oil Cooler	<u>FAIR</u> • Attn
OPERATING SYSTEM	
Swing	<u>FAIR</u> • Attn
Travel	<u>FAIR</u> • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY
Operator's Seat	<u>FAIR</u> • <u>Attn</u> 穴、破れあり HOLE, CUTS
Glasses	<u>FAIR</u> • Attn
AirCon	A/C • H/C • H only • C only • <u>None</u>
BOOM / ARM / BKT	
Boom	<u>FAIR</u> • Attn
Boom Cylinder	<u>FAIR</u> • Attn
Arm	<u>FAIR</u> • Attn
Arm Cylinder	<u>FAIR</u> • Attn
ATTACHMENT	<u>FAIR</u> • <u>Attn</u> ガタあり LOOSE
BKT Cylinder	<u>FAIR</u> • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / <u>OTHER</u> / FORK GRAB)
Lever	LONG • <u>WRIST</u>
Multi	<u>MULTI</u> • 2 • NO
ARM-CRANE	YES • <u>NO</u>
BLADE	<u>YES</u> • NO
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> • Attn
Piping	<u>YES</u> • NO Breaker only • <u>Multi</u>
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。