

**INSPECTION SHEET 検品書**  
**WHEEL LOADER タイヤショベル**

INSPECTION DATE	2026/6/2	MAKE	KOMATSU	MODEL	WA100-5
SERIAL	70083		STAMP	W108-70083	
HR METER	4125	HR	Odometer	12413	km
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		TIRE SIZE	16.9-24	
YEAR	2003		YR		

**ENGINE : MODEL** 4D102E-2 **S/N** 26322929

Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	

**OPERATION PUMP**

Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	

**COOLING SYSTEM**

Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	

**TRANSMISSION & TRAVEL**

T/M TYPE	<u>PS</u> · DD	
Transmission	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
FOOT BRAKE	<u>FAIR</u> · Attn	
PARKING BRAKE	<u>FAIR</u> · Attn	

**INTERIOR** See Photos. 写真参照

INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	損傷あり A LITTLE DAMAGED
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	

**FRONT & CYLINDERS**

Arm	<u>FAIR</u> · Attn	
Bell crank	<u>FAIR</u> · Attn	
Bucket	<u>FAIR</u> · Attn	
Articulate	<u>FAIR</u> · Attn	

**UNDERCARRIAGE :** See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

TIRE WEAR FAIR · WORN · UNEVEN WEAR

**COMMENT**  
.....  
.....  
.....

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL YES · NO

**ATTACHMENTS**

STD BKT YES · OTHER  
BLADE YES · NO Piping for Tilt YES · NO

**COMMENT**  
コンクリート付着あり CONCRETE STAINS  
.....  
.....  
.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。