

## INSPECTION SHEET 検品書

## TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2026/6/15	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE			
MAKE	KATO		MODEL	NK-75M-V		
SERIAL	3010312		STAMP	FD3WDA-50217		
HR METER	UNKNOWN	HR	Odometer	137178 km	YEAR	YR
CHASSIS	MODEL	U-FD3WDAD改	No.	50217	TIRE	225/90R17.5

<b>ENGINE(CRANE) : MODEL</b> W06E		<b>S/N</b>	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
<b>ENGINE(CHASSIS) : MODEL</b>		<b>S/N</b>	
Oil leakage	FAIR · Attn	*1	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
<b>OPERATION PUMP</b>			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
<b>OPERATING SYSTEM</b>			
Computer	OK · NG		
Swing	FAIR · Attn		
Travel	FAIR · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	AT · MT	No. OF GEARS	5 GEARS
Transmission	FAIR · Attn		
No. of DRIVE WHEELS	2 WD		
Travel	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	FAIR · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり	TINY CUTS
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · NONE		

<b>CRANE</b>	
WEIGHT	-
HOOK	4.9t, BALL
<b>BOOM</b>	
MAIN BOOM	
BOOM TOTAL	
No. of Section	4 SECTIONS
TOP SHEAVE	YES · NO
JIB	STD · PWR
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
<b>COMMENT</b>	
左右タイヤ側面ひび割れあり REAR TIRE SIDEWALLS: CRACKED	
<b>OUTRIGGERS</b>	
OUTRIGGERS	FAIR · Attn H-TYPE
FRONT JACK	YES · NO
<b>COMMENT</b>	
クレーン部ヒーター付 CRANE CAB: W/HEATER	
*1 ブロック付近油漏れあり AROUND ENGINE BLOCK: OIL LEAKING	
<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。