

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/6/11	CATEGORY	自走式杭打機 PILE DRIVER			
MAKE	SHIROTA		MODEL	S-15		
SERIAL	528		STAMP	NOT FOUND		
HR METER	9892	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB	<input checked="" type="radio"/> CAB /	ROPS CNP /	CNP /	NONE	
	SHOE	500G PADS	TIRE			

ENGINE	MODEL	4JJ1	S/N	211666		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		Oil	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
Sound	<input checked="" type="radio"/> FAIR · Attn		EPA	YES · <input checked="" type="radio"/> NO		

CONDITION	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
--	---	-----------	---------------------------

COMMENT

バックカメラ不良 BACK MONITOR: MALFUNCTION

A/C

右Rアウトリガーにじみあり REAR RIGHT OUTRIGGER: OIL OOZING

ポンプホースにじみあり SOME PUMP HOSE: OIL OOZING

旋回ガタあり SWING: LOOSE

シート破れあり SEAT: TORN

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
--	---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。