

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/7/22	MAKE	HITACHI	MODEL	LX70-5
SERIAL	41WP005176	STAMP	L705-5176		
HR METER	2969	HR	Odometer	UNKNOWN	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	16.9-24 10PR	YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	YES · ☒ NO	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	*1
Oil Cooler	☒ FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	☒ PS · DD	
Transmission	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
FOOT BRAKE	☒ FAIR · Attn	
PARKING BRAKE	☒ FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☒ FAIR · Attn	破れ大 TORN
Glasses	☒ FAIR · Attn	
AirCon	A/C · H/C · ☒ H only · C only · None	
FRONT & CYLINDERS		
Arm	☒ FAIR · Attn	*2
Bell crank	☒ FAIR · Attn	
Bucket	☒ FAIR · Attn	*3
Articulate	☒ FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt ☒ YES · NO
COMMENT	
マフラータイコ先端破損あり MUFFLER: BROKEN	
A/Cスイッチはあるが使用できない、ヒーターのみ使用可	
A/C: NOT WORKING, ONLY HEATER: WORKING	
左ドアラッチ不良(中からは開く)	
LEFT DOOR LATCH: MALFUNCTION (JUST ABLE TO OPEN FROM INSIDE)	
*1 ラジエータマスク、ビビリ音あり	
*1 RADIATOR COVER: RATTLING NOISES	
*2 右シリンダーにじみあり(吸着マット付)、左右アームねじれあり	
*2 RIGHT CYLINDER: OIL Oozing (W/ABSORPTION MAT),	
ARMS: DISTORTED	
*3 シリンダーにじみあり(吸着マット付)	
*3 CYLINDER: OIL Oozing (W/ABSORPTION MAT)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。