

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/7/10	MAKE	YANMAR	MODEL	C10R		
SERIAL	10617C			STAMP	10617C		
HR METER	928	HR	Odometer	km	YEAR	1997	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	230R	TIRE	

ENGINE :		MODEL L100ADEFW1 S/N		41536	
Oil leakage	FAIR	Attn	油漏れ、汚れあり OIL LEAKING, OIL STAINS		
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn	黒煙小 A LITTLE BLACK FUMES		
US EPA	YES	NO			
OPERATION PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	PS	DD		No. OF GEARS	2 GEARS
Transmission	FAIR	Attn			
Travel	FAIR	Attn			
Swing	FAIR	Attn			
Articulate	FAIR	Attn			
FOOT BRAKE	FAIR	Attn			
PARKING BRAKE	FAIR	Attn	効き甘い BRAKE: LOOSE		
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	破れあり CUTS		
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None

MAIN FRAME						
MAIN FLAME		(FAIR)	▪	Attn		
VESSEL						
VESSEL		FAIR	▪	(Attn)	ガタあり LOOSE	
REAR GATE TYPE		(NORMAL)			▪	L-GATE (FLAT)
REAR GATE		(FAIR)	▪	Attn		
UNDERCARRIAGE: See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						4
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT 						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。