

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/6/29	MAKE	MITSUBISHI	MODEL	FD40D		
SERIAL	F19C-50418			STAMP	F19C-50418		
HR METER	5534	HR	Odometer	-	km	YEAR	YR
CAB/CNP	CAB	/	CNP	/	NONE	TIRE SIZE	F: 300-15/8.00 R: 7.00-12/5.00
MAX LIFTING HEIGHT	3.0	m	VIEW	MONO	FORK LENGTH	1800	mm
FORK SPEC							

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C
HYDRAULICS		
MAST Cylinder	FAIR	Attn
TILT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR
COMMENT	
ノーパンクタイヤ SOLID TIRES	
ステアリングシリンダー付近油漏れ大	
AROUND STEERING CYLINDER: SEVERE OIL LEAKING	
*1 白煙大のため少ししか走行できない	
(負荷が掛かるとエンストしそうになる)	
*1 ONLY ABLE TO TRAVEL A SHORT DISTANCE	
(MUCH WHITE FUMES	
& ALMOST ENGINE STALLING WITH ENGINE LOAD INCREASING)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。