

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/7/8	MAKE	KOMATSU	MODEL	D65PX-15E0	
SERIAL	70053			STAMP	KMT0D100J01070053	
HR METER	7387	HR	SHOE	950LGP	YEAR	YR
BLADE	STRAIGHT	ST/TILT	PAT / ANGLE / OTHER	CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		6D114E-3	S/N	26852983
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
OPERATION PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	PS	DD	DIFF. STEERING	YES · NO
Transmission	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C · H only · C only · None		
BLADE & CYLINDERS				
BLADE	FAIR	Attn		
CYLD.(R)	FAIR	Attn		
CYLD.(L)	FAIR	Attn		
TILT CYLD	FAIR	Attn		
ANGLE CYLD	FAIR	Attn		

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。