

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/8	MAKE	HITACHI	MODEL	ZX135US-5B
SERIAL	HCMDAEA0P00098900		STAMP	HCMDAEA0P00098900	
HR METER	7145	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL S/N

Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	

MAIN PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM

Swing	FAIR · Attn	
Travel	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり HUGE CUT
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT

Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	にじみ、傷あり OIL Oozing, SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

シューパッド摩耗大、剥がれ多数あり RUBBER PADS: ALMOST GONE

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
-----	---

Lever	LONG · WRIST
-------	--------------

Multi	MULTI · 2 · NO
-------	----------------

ARM-CRANE	YES · NO
-----------	----------

BLADE	YES · NO
-------	----------

OFFSET	YES · NO
--------	----------

OFFSET Cylinder	FAIR · Attn
-----------------	-------------

Piping	YES · NO Breaker only · Multi
--------	-------------------------------

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。