

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/23	MAKE	KUBOTA	MODEL	RX-306E
SERIAL	24230		STAMP	24230	
HR METER	5072	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300R	

ENGINE : MODEL		D1703	S/N	7JK6531
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れ小、カバーあり CUTS, W/SEAT COVER	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT 					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG ▪ (WRIST)				
Multi	MULTI ▪ (2) ▪ NO				
ARM-CRANE	(YES) ▪ NO				
BLADE	(YES) ▪ NO				
OFFSET	(YES) ▪ NO				
OFFSET Cylinder	(FAIR) ▪ Attn				
Piping	YES ▪ (NO)	Breaker only	▪ Multi		
COMMENT ボディ右側面カバー変形あり FRONT RIGHT SIDE COVER: DISTORTED 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。