

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |             |
|-----------------|----------------------------------------|------|---------|-------------------|-------------|
| INSPECTION DATE | 2026/6/23                              | MAKE | HITACHI | MODEL             | ZX225USRK-3 |
| SERIAL          | HCM1U600H00219579                      |      | STAMP   | HCM1U600H00219579 |             |
| HR METER        | 13683                                  | HR   | YEAR    | YR                |             |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 600G              |             |

  

|                                                                               |                                                                |  |
|-------------------------------------------------------------------------------|----------------------------------------------------------------|--|
| <b>ENGINE : MODEL</b> 4HK1 <b>S/N</b> 488091                                  | <b>UNDERCARRIAGE :</b> See Photos. 写真参照                        |  |
| Oil leakage FAIR · Attn                                                       | RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2 |  |
| Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE                                | <b>COMMENT</b>                                                 |  |
| Sound FAIR · Attn                                                             |                                                                |  |
| Oil FAIR · Attn                                                               |                                                                |  |
| Exhaust Color FAIR · Attn                                                     |                                                                |  |
| US EPA YES · NO                                                               |                                                                |  |
| <b>MAIN PUMP</b>                                                              |                                                                |  |
| Sound FAIR · Attn                                                             | BKT (STD / SLOPE / NARROW / SKELETON / OTHER ( )               |  |
| Oil leakage FAIR · Attn                                                       | Lever LONG · WRIST                                             |  |
| Power FAIR · Attn                                                             | Multi MULTI · 2 · NO                                           |  |
| <b>COOLING SYSTEM</b>                                                         |                                                                |  |
| Radiator FAIR · Attn                                                          | ARM-CRANE YES · NO                                             |  |
| Oil Cooler FAIR · Attn                                                        | BLADE YES · NO                                                 |  |
| <b>OPERATING SYSTEM</b>                                                       |                                                                |  |
| Swing FAIR · Attn *1                                                          | OFFSET YES · NO                                                |  |
| Travel FAIR · Attn                                                            | OFFSET Cylinder FAIR · Attn                                    |  |
| <b>INTERIOR See Photos. 写真参照</b>                                              |                                                                |  |
| INTERIOR COND. CLEAN · FAIR · DIRTY                                           | Piping YES · NO Breaker only · Multi 5                         |  |
| Operator's Seat FAIR · Attn 切れあり TORN                                         | <b>COMMENT</b>                                                 |  |
| Glasses FAIR · Attn                                                           |                                                                |  |
| AirCon A/C · H/C · H only · C only · None                                     |                                                                |  |
| <b>BOOM / ARM / BKT</b>                                                       |                                                                |  |
| Boom FAIR · Attn ガタあり LOOSE                                                   |                                                                |  |
| Boom Cylinder FAIR · Attn *2                                                  | HRメーターの百の位が見えづらい MONITOR: PARTLY NOT DISPLAYING                |  |
| Arm FAIR · Attn                                                               | E/Gバラつきあり ENGINE SPEED: UNSTABLE                               |  |
| Arm Cylinder FAIR · Attn ガタ大 MUCH LOOSE                                       | タービン音あり TURBO NOISES                                           |  |
| ATTACHMENT FAIR · Attn 摩耗、変形あり WORN, DENT                                     | *1 ガタ、ベアリング摩耗あり SWING: LOOSE, BEARING: WORN                    |  |
| BKT Cylinder FAIR · Attn                                                      | *2 右油漏れ大 RIGHT CYLINDER: SEVERE OIL LEAKING                    |  |
| <b>RUST of BODY</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2 |                                                                |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。