

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/7/27	MAKE	CAT	MODEL	962MZ		
SERIAL	CAT0962MUSA820122			STAMP	CAT0962MUSA820122		
HR METER	5966	HR	Odometer	20813	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5R25		

ENGINE : MODEL		C7.1	S/N	J7A01594
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY				
Operator's Seat	FAIR • Attn				
Glasses	FAIR • Attn	Fひび割れあり WINDSHIELD: CRACKED			
AirCon	A/C •	H/C	H only	C only	None

FRONT & CYLINDERS

Arm	FAIR · Attn	*1
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

TIRE WEAR (FAIR • WORN • UNEVEN WEAR)

COMMENT

右Fタイヤ亀裂あり FRONT RIGHT TIRE SIDEWALL: A LITTLE DAMAGED

STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING

RIDE CONTROL	☒ YES	☐ NO
--------------	--------------------------------------	--------------------------

ATTACHMENTS

STD BKT	☒ YES • ☐ OTHER
---------	--

BLADE	YES	☒ NO	Piping for Tilt	YES	☒ NO
-------	-----	-------------------------------------	-----------------	-----	-------------------------------------

COMMENT

*1 右シリンダー油漏れ小 RIGHT CYLINDER: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **3**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。