

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/7	MAKE	CAT	MODEL	313DCR
SERIAL	CAT0313DLLCE00701		STAMP	CAT0313DLLCE00701	
HR METER	5561	HR	YEAR	2012	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		C4.2	S/N	JKH18668
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
None				
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos.						写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							3
COMMENT							
シューパッド剥がれ多数あり MANY RUBBER PADS: PEELED OFF							
BKT	(STD)	/SLOPE / NARROW / SKELETON / OTHER()					
Lever	LONG	▪ (WRIST)					
Multi	(MULTI) ▪ 2 ▪ NO						
ARM-CRANE	(YES) ▪ NO						
BLADE	YES ▪ (NO)						
OFFSET	YES ▪ (NO)						
OFFSET Cylinder	FAIR ▪ Attn						
Piping	(YES) ▪ NO	Breaker only ▪ (Multi)					
COMMENT							
ブーム背面ホースひび割れあり SOME HOSE AROUND BOOM: CRACKED							
バックカメラ不良 BACK MONITOR: MALFUNCTION							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。