

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/9	MAKE	KUBOTA	MODEL	U-40
SERIAL	NO PLATE		STAMP	70528	
HR METER	5570	HR	YEAR	2008	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL		V2203	S/N	08A0644
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn	ガタあり LOOSE		
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn	破れあり CUTS		
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn	油漏れあり OIL LEAKING		
Arm	FAIR · Attn	ガタあり LOOSE		
Arm Cylinder	FAIR · Attn	にじみあり OIL OOZING		
ATTACHMENT	FAIR · Attn	ガタあり LOOSE		
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照		3
COMMENT		
右走行モーターにじみあり RIGHT TRAVEL MOTOR: OIL OOZING		
シューパッド剥がれ多数あり MANY RUBBER PADS: PEELED OFF		
BKT	(STD) / (SLOPE) / (NARROW) / (SKELETON) / OTHER()	
Lever	LONG • (WRIST)	
Multi	(MULTI) • 2 • NO	
ARM-CRANE	YES • (NO)	
BLADE	(YES) • NO	
OFFSET	YES • (NO)	
OFFSET Cylinder	FAIR • Attn	
Piping	(YES) • NO Breaker only • (Multi)	
COMMENT		
リペイントあり REPAINTED		
スイングガタあり SWING PART: LOOSE		
モニター表示切替ボタン接触不良 (ボタンが勝手に押される)		
DISPLAY SWITCH BUTTON: LOOSE CONNECTION		
(AUTOMATICALLY SWITCHING)		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。