

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/21	MAKE	HITACHI	MODEL	ZX210K-5B
SERIAL	HCMDCKA6C00304887			STAMP	HCMDCKA6C00304887
HR METER	21877	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 4HK1 S/N	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れ大 TORN
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn 右油漏れあり RIGHT CYLINDER: OIL LEAKING
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
ATTACHMENT	FAIR · Attn
BKT Cylinder	FAIR · Attn 油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
発電機付(リフマグ搭載仕様):	
鍵付いていない(動作未確認)、HRメーター: 752HR?	
W/GENERATOR (FOR MAGNET USE):	
NO KEY (OPERATION: NOT CHECKED), HR METER: 752HR?	
MAKE: DENYO TLG-7.5ESK-3823518	
A/C効かない A/C: MALFUNCTION	
左サイドラジエータカバー変形あり、20%くらいしか開かない	
LEFT SIDE COVER FOR RADIATOR: A LITTLE DEFORMED,	
JUST ABLE TO OPEN ABOUT 20% OF NORMAL	
アタッチメントなし WITHOUT ATTACHMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。