

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |           |
|-----------------|----------------------------------------|------|---------|-------------------|-----------|
| INSPECTION DATE | 2026/7/1                               | MAKE | KOMATSU | MODEL             | PC138US-8 |
| SERIAL          | 31631                                  |      | STAMP   | KMTPC189T01031631 |           |
| HR METER        | 7092                                   | HR   | YEAR    | YR                |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 500G PADS         |           |

|                           |       |                              |                                |        |
|---------------------------|-------|------------------------------|--------------------------------|--------|
| ENGINE : MODEL            |       | 4D95LE-5                     | S/N                            | 545873 |
| Oil leakage               | FAIR  | Attn                         |                                |        |
| Blow-By                   | FAIR  | Attn                         | A LITTLE · MIDDLE · SEVERE     |        |
| Sound                     | FAIR  | Attn                         |                                |        |
| Oil                       | FAIR  | Attn                         |                                |        |
| Exhaust Color             | FAIR  | Attn                         |                                |        |
| US EPA                    | YES   | NO                           |                                |        |
| MAIN PUMP                 |       |                              |                                |        |
| Sound                     | FAIR  | Attn                         |                                |        |
| Oil leakage               | FAIR  | Attn                         |                                |        |
| Power                     | FAIR  | Attn                         |                                |        |
| COOLING SYSTEM            |       |                              |                                |        |
| Radiator                  | FAIR  | Attn                         |                                |        |
| Oil Cooler                | FAIR  | Attn                         |                                |        |
| OPERATING SYSTEM          |       |                              |                                |        |
| Swing                     | FAIR  | Attn                         | ガタあり SWING: LOOSE              |        |
| Travel                    | FAIR  | Attn                         |                                |        |
| INTERIOR See Photos. 写真参照 |       |                              |                                |        |
| INTERIOR COND.            | CLEAN | FAIR                         | DIRTY                          |        |
| Operator's Seat           | FAIR  | Attn                         |                                |        |
| Glasses                   | FAIR  | Attn                         |                                |        |
| AirCon                    | A/C   | H/C · H only · C only · None |                                |        |
| BOOM / ARM / BKT          |       |                              |                                |        |
| Boom                      | FAIR  | Attn                         |                                |        |
| Boom Cylinder             | FAIR  | Attn                         | 両側油漏れあり CYLINDERS: OIL LEAKING |        |
| Arm                       | FAIR  | Attn                         |                                |        |
| Arm Cylinder              | FAIR  | Attn                         |                                |        |
| ATTACHMENT                | FAIR  | Attn                         | *1                             |        |
| BKT Cylinder              | FAIR  | Attn                         | 油漏れあり OIL LEAKING              |        |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。