

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |       |                   |        |
|-----------------|----------------------------------------|------|-------|-------------------|--------|
| INSPECTION DATE | 2026/7/13                              | MAKE | CAT   | MODEL             | 320D-E |
| SERIAL          | CAT0320DHBWZ08141                      |      | STAMP | CAT0320DHBWZ08141 |        |
| HR METER        | 9674                                   | HR   | YEAR  | YR                |        |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE  | 790G              |        |

|                           |                      |                              |                            |          |
|---------------------------|----------------------|------------------------------|----------------------------|----------|
| ENGINE : MODEL            |                      | C6.4                         | S/N                        | GDC72407 |
| Oil leakage               | FAIR                 | Attn                         |                            |          |
| Blow-By                   | FAIR                 | Attn                         | A LITTLE · MIDDLE · SEVERE |          |
| Sound                     | FAIR                 | Attn                         |                            |          |
| Oil                       | FAIR                 | Attn                         |                            |          |
| Exhaust Color             | FAIR                 | Attn                         |                            |          |
| US EPA                    | YES                  | NO                           |                            |          |
| MAIN PUMP                 |                      |                              |                            |          |
| Sound                     | FAIR                 | Attn                         |                            |          |
| Oil leakage               | FAIR                 | Attn                         |                            |          |
| Power                     | FAIR                 | Attn                         |                            |          |
| COOLING SYSTEM            |                      |                              |                            |          |
| Radiator                  | FAIR                 | Attn                         |                            |          |
| Oil Cooler                | FAIR                 | Attn                         |                            |          |
| OPERATING SYSTEM          |                      |                              |                            |          |
| Swing                     | FAIR                 | Attn                         |                            |          |
| Travel                    | FAIR                 | Attn                         |                            |          |
| INTERIOR See Photos. 写真参照 |                      |                              |                            |          |
| INTERIOR COND.            | CLEAN · FAIR · DIRTY |                              |                            |          |
| Operator's Seat           | FAIR                 | Attn                         | 破れあり HUGE CUTS             |          |
| Glasses                   | FAIR                 | Attn                         |                            |          |
| AirCon                    | A/C                  | H/C · H only · C only · None |                            |          |
| BOOM / ARM / BKT          |                      |                              |                            |          |
| Boom                      | FAIR                 | Attn                         |                            |          |
| Boom Cylinder             | FAIR                 | Attn                         |                            |          |
| Arm                       | FAIR                 | Attn                         |                            |          |
| Arm Cylinder              | FAIR                 | Attn                         | 油漏れあり OIL LEAKING          |          |
| ATTACHMENT                | FAIR                 | Attn                         |                            |          |
| BKT Cylinder              | FAIR                 | Attn                         |                            |          |

|                                                                               |                                             |   |         |              |    |       |   |
|-------------------------------------------------------------------------------|---------------------------------------------|---|---------|--------------|----|-------|---|
| UNDERCARRIAGE : See Photos. 写真参照                                              |                                             |   |         |              |    |       |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                  |                                             |   |         |              |    |       | 3 |
| COMMENT<br><br>                                                               |                                             |   |         |              |    |       |   |
| BKT                                                                           | (STD / SLOPE / NARROW / SKELETON / OTHER( ) |   |         |              |    |       |   |
| Lever                                                                         | LONG                                        | ▪ | (WRIST) |              |    |       |   |
| Multi                                                                         | (MULTI)                                     | ▪ | 2       | ▪            | NO |       |   |
| ARM-CRANE                                                                     | (YES)                                       | ▪ | NO      |              |    |       |   |
| BLADE                                                                         | YES                                         | ▪ | (NO)    |              |    |       |   |
| OFFSET                                                                        | YES                                         | ▪ | (NO)    |              |    |       |   |
| OFFSET Cylinder                                                               | FAIR                                        | ▪ | Attn    |              |    |       |   |
| Piping                                                                        | YES                                         | ▪ | (NO)    | Breaker only | ▪  | Multi |   |
| COMMENT<br>旋回モーター周りホースひび割れあり<br>SOME HOSE AROUND SWING MOTOR: CRACKED<br><br> |                                             |   |         |              |    |       |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)          |                                             |   |         |              |    |       | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。