

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE		2026/8/20		MAKE	HITACHI		MODEL	CX500	
SERIAL No.	PLATE : 243P002231				STAMP	243P002231			
HR METER	9319		HR	SHOE	760FLAT		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · ☒ SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	未確認 NOT CHECKED
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 1, 6m × 1, 3m × 1	
BOOM TOTAL	28m	
TOP SHEAVE	☒ YES · NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1
COMMENT		
WEIGHT	3	
HOOK	50t, 30t, BALL	
FREE FALL	YES · ☒ NO	
LIFTER	YES · ☒ NO	
COMMENT		
CABスライドドア開閉不良		
CAB SLIDE DOOR: MALFUNCTION TO OPEN or CLOSE		
駐車場側に別置き: 9mブーム、30tフック、ボールフック		
9m BOOM, 30t HOOK, & BALL HOOK: NOT ATTACHED		
@NARITA YARD		
BOOM: TOP, BOTTOM, 6m × 1, 3m × 1		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。