

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/7/16	MAKE	KOMATSU	MODEL	D37PX-24
SERIAL	90323			STAMP	KMT0D131HNA090323 (HARD TO READ)
HR METER	914	HR	SHOE	600LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE :		MODEL		4D95LE-7		S/N		826721	
Oil leakage	FAIR	·	Attn						
Blow-By	FAIR	·	Attn	A LITTLE · MIDDLE · SEVERE					
Sound	FAIR	·	Attn						
Oil	FAIR	·	Attn						
Exhaust Color	FAIR	·	Attn						
US EPA	YES	·	NO						
OPERATION PUMP									
Sound	FAIR	·	Attn						
Oil leakage	FAIR	·	Attn						
Power	FAIR	·	Attn						
COOLING SYSTEM									
Radiator	FAIR	·	Attn						
Oil Cooler	FAIR	·	Attn						
TRANSMISSION & TRAVEL									
T/M TYPE	PS	·	DD	DIFF. STEERING			YES · NO		
Transmission	FAIR	·	Attn						
Travel	FAIR	·	Attn						
INTERIOR See Photos. 写真参照									
INTERIOR COND.	CLEAN	FAIR · DIRTY							
Operator's Seat	FAIR	·	Attn						
Glasses	FAIR	·	Attn						
AirCon	A/C	·	H/C	·	H only	·	C only	·	None
BLADE & CYLINDERS									
BLADE	FAIR	·	Attn						
CYLD.(R)	FAIR	·	Attn						
CYLD.(L)	FAIR	·	Attn						
TILT CYLD	FAIR	·	Attn						
ANGLE CYLD	FAIR	·	Attn						

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。