

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/17	MAKE	KATO	MODEL	HD820-7
SERIAL	KWJ51E01TL0005674		STAMP	5674	
HR METER	3844 / 38??		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		4HK1	S/N	808772
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn			
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
ATTACHMENT	FAIR · Attn	ガタあり LOOSE		
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE :						See Photos.						写真参照							
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																		4	
COMMENT 																			
BKT		(STD / SLOPE / NARROW / SKELETON / OTHER()																	
Lever		LONG ▪				(WRIST)													
Multi		(MULTI) ▪				2 ▪ NO													
ARM-CRANE		(YES) ▪				NO													
BLADE		YES ▪				(NO)													
OFFSET		YES ▪				(NO)													
OFFSET Cylinder		FAIR ▪				Attn													
Piping		(YES) ▪				NO				Breaker only ▪				(Multi)					
COMMENT 																			
HRメーター一片方表示不良 ONE OF HR METERS: PARTLY NOT DISPLAYING 																			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																		4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。