

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/20	MAKE	KUBOTA	MODEL	U-20-3A
SERIAL	KBCBZ46AAN3A53178			STAMP	KBCBZ46AAN3A53178
HR METER	479	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	250G PADS

ENGINE : MODEL		S/N	1NA3578
Oil leakage	☒ FAIR · Attn		
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR · Attn		
Oil	☒ FAIR · Attn		
Exhaust Color	☒ FAIR · Attn		
US EPA	YES · ☒ NO		
MAIN PUMP			
Sound	☒ FAIR · Attn		
Oil leakage	☒ FAIR · Attn		
Power	☒ FAIR · Attn		
COOLING SYSTEM			
Radiator	☒ FAIR · Attn		
Oil Cooler	☒ FAIR · Attn		
OPERATING SYSTEM			
Swing	☒ FAIR · Attn		
Travel	☒ FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	☒ CLEAN · FAIR · DIRTY		
Operator's Seat	☒ FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · ☒ None		
BOOM / ARM / BKT			
Boom	☒ FAIR · Attn		
Boom Cylinder	☒ FAIR · Attn		
Arm	☒ FAIR · Attn		
Arm Cylinder	☒ FAIR · Attn		
ATTACHMENT	☒ FAIR · Attn		
BKT Cylinder	☒ FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	YES · ☒ NO
BLADE	☒ YES · NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO Breaker only · ☒ Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。